

Outgoing
COO 70019
OK

OGMCOAL - Fwd: Centennial Complete Inspection

From: Karl Houskeeper <karlhouskeeper@utah.gov>
To: OGMCOAL <OGMCOAL@utah.gov>, Steve Christensen <stevechristensen@utah.gov...>
Date: 8/13/2012 3:43 PM
Subject: Fwd: Centennial Complete Inspection
Attachments: DSC00105.JPG; DSC00093.JPG; DSC00094.JPG; DSC00095.JPG; DSC00096.JPG; DSC00097.JPG; DSC00098.JPG; DSC00099.JPG; DSC00100.JPG; DSC00101.JPG; DSC00102.JPG; DSC00103.JPG; DSC00104.JPG

----- Forwarded message -----

From: **Karl Houskeeper** <karlhouskeeper@utah.gov>
Date: Mon, Aug 13, 2012 at 3:26 PM
Subject: Centennial Complete Inspection
To: J D Leonard <jleonard@coalsource.com>, jmarshall@coalsource.com

JD/Jay,

Attached are some pictures taken at the Centennial mine. These pictures correlate to actions items that need to be taken care of immediately. Some items are from previous inspections or are re-occurring items from areas that have been problems in the past.

ITEMS:

Culvert outlet along main road below lamp house entrance right side looking up-canyon is beginning to build with sediment. Picture DSC00098.

Culvert inlet (undisturbed) by oil storage building is beginning to build with sediment and weeds. Re-occurring item. Picture DSC00099.

Culvert outlet along main road left side looking up-canyon just below entrance to shop area is smashed and building with sediment. Picture DSC00097

Thistle along main road just above entrance to shop area left side of road looking up-canyon. From prior inspections. Has not been treated and heads have not been removed. Picture DSC00096

Drainage from upper most load-out and office building is staying channelized on the road creating erosion on road. Road needs to be re-graded to divert water off it. Picture DSC00093

Thistle in storage area above shop area has been sprayed. Heads were not removed allowing seeds to still spread. Heads need to be removed and disposed of properly. From prior inspections
Pictures DSC00094 & DSC00095.

Thistle in sediment cells below bathhouse area along main road and plastic sheeting in pond. Pictures DSC00100, DSC000101, DSC00102, DSC00103 & DSC00104

Topsoil sign is down off of pole. Sign laying on ground. Needs to be re-installed. pile is below lower bathhouse entrance. Picture DSC00105

There may be some communication problems between required work and workers understanding the scope of work. This e-mail and pictures should help in eliminating any confusion. Several warnings have been given on several of the listed items. Items need to be resolved before the next inspection to

avoid enforcement action.

Any questions please feel free to call for clarification.

Thanks,
Karl

--

Karl R. Houskeeper
Environmental Scientist III
Division of Oil, Gas and Mining
319 North Carbonville Road, Suite C
Price, Utah 84501
Phone: (435) 613-3730
Fax: (435) 613-3739
Email: karlhouskeeper@utah.gov

--

Karl R. Houskeeper
Environmental Scientist III
Division of Oil, Gas and Mining
319 North Carbonville Road, Suite C
Price, Utah 84501
Phone: (435) 613-3730
Fax: (435) 613-3739
Email: karlhouskeeper@utah.gov























